# 200W USB-C 6-PORT PD GAN CHARGER

1

Connect the included C5 power cable to the C5 connector on the rear of the charger.

2

Plug the power cable directly to a power outlet.

3

The LED Indicator light will Illuminate white when receiving power.

4

The 200W charger can be laid flat horizontally on the supported rubber feet or vertically using the included Desktop Stand.

5

Plug in cables (sold separately) to the charger's USB-C PD ports.
We always recommend using certified charging cables.
EMARK cables are required to reach wattage above 60W.

6

Connect and charge up to six USB-C devices simultaneously
Total max output: 200W.
When connecting devices to all six PD ports, connect your largest device to the PD1 port.

Standard operating temperature 150°F / 65°C

CHARGING

7

PD1   MAX 140W   PD1
MagSafe 3
PD2   PD2
PD3   PD3

When connected to PD1 or PD2, supported device can charge with a max output of 140W.
Only one device can be connected at a time to either port in order to achieve 140W charging.
USB-C to MagSafe 3 Cable must be used in order to achieve 140W output through PD1 or PD2.

8

PD2   PD2
PD3   MAX 100W   PD3
PD4   PD4
PD5   PD5

When connected to PD3 or PD4, supported device can charge with a max output of 100W.

9

PD4   PD4
PD5   MAX 20W   PD5
PD6   PD6

When connected to PD5 or PD6, supported device can charge with a max output of 20W.

Please refer to the Power Schematic in the user manual for actual power outputs, depending on the number of connected devices