# USB-C MULTIPORT MX ADAPTER

> **!** **Important!**
> SiliconMotion software must be installed for both HDMI ports to function (see manual for full instructions).

**1** Connect the adapter to an USB-C port on your device.

2 Connect two HDMI-enabled monitors for dual 4K HDMI display output.
One HDMI supports up to 60Hz, the other 30Hz

3 Use the USB-C PD charging port to power your device – up to 100W
~15W of power used for operation
USB-C charging port does not support video or data

4 Connect an RJ45 network cable to the adapter's Gigabit Ethernet port.

5 Use the USB-C and two USB-A 3.0 ports for data transfer and file backup – up to 5 Gbps each.
Does not support charging or CD readers, including Apple SuperDrive

6 Insert microSD or SD cards into the card reader slots.