# USB-C FAST CHARGING CABLE FOR APPLE WATCH

1

To start charging, please connect the Cable to a USB-C charger or port that provides a 5W output or more.

2

Place your Apple Watch on the magnetic charger; you should see the charging indicator animation.
Please note that fast-charging is only supported for Series 7, 8, 9, Ultra, and Ultra 2 models.

3

Remove your Apple Watch from the charger when it is fully charged.

Charging Cable is also compatible with AirPods Pro (2nd generation) and AirPods (3rd generation).